



# Safe Sec Engineers

Deals in :

● ISI FIRE EXTINGUISHERS & HYDRANT SPRINKLER SYSTEM ● FIRE ALARM & SAFETY EQUIPMENTS

5425

105-A, SUBHASH NAGAR,  
N.E.B., ALWAR-301001 (RAJ.)

Mob. : 7742638775  
0144-2370539 (R)

E-mail : safesecengineers@rediffmail.com

Ref. No.....

Date. 12/01/2025

## FIRE SAFETY CERTIFICATE

CHILDRENS ACADMEY COLLEGE OF EDUCATION  
DELHI ROAD, ALWAR

S. NO.	PART & PARA IN DETAIL AUDIT REPORT	OBSERVATION	RECOMMENDATION	ACTION BY
1	Fire Extinguishers	Fire Extinguishers of ABC type only are installed in the entire Educational area.	Fire Extinguishers placement has been checked based on hazards and type of fire as per IS: 2190. Access to extinguishers to be kept obstruction free for quick response.	We Check the fire extinguisher cylinder time to time any if any problem is found then immediately call the person of company.
2	Emergency Fire Exit Plan	They have placed proper Fire exit plan over there, suggested for emergency duty roster to be repaired and implemented.	Printed copies of the emergency fire escape plan are provided and efforts are made to remove any obstructions on the way out into the premises	We follow the recommendation regularly.
3	Means of escape and open space around the building.	Main gate round the clock manned by CCTV cameras In case of fire emergency the fire fighting vehicles can approach the building from front side only.	A clear access way must be maintained in front of the Hospital gate for speedy movement fire fighting appliances. Approach road may be kept free for movement of fire vehicles in case of fire emergency.	Someone from our hospital staff take care throughout the day to ensure that there is no obstruction at any emergency time during movement and if any obstruction is found it is removed.
4	Life safety, directional signage inside the Building	Emergency exit signage's provided in entire Building	Direction to exit must be conspicuously and unambiguously marked with exit signage's	We have put up signage of fire exit and fire escape plans throughout the hospital area
5	Alternate source of electric supply and emergency light	Inverter is installed for supply of uninterrupted electricity to the Building	The standby inverter must be capable of performing few operations simultaneously during an emergency when normal power supply breaks down	We have proper power back up inverter which works properly when normal supply break down
6	Educational Building area	Good housekeeping being maintained throughout Building area. Proper color coding, waste bins should be provided wherever necessary.	Good housekeeping practices should be continued and records should be maintained	We have housekeeping staff to along with College staff for all recommended checks
7	Basic first aid and Fire Fighting Training	During audit it was realized that staff working in College have basic knowledge of first aid firefighting. Use & operation of fire extinguishers available with Building. It is revealed that first aid fire fighting training is being given to staff on regular basis but no record is being maintained	All the employees & staff who are always present in the College are required to be regularly trained in various aspects of fire prevention, fire protection & fire extinction including handling of first aid & fire fighting equipments	We give training to escape from any emergency or to use fire extinguisher which help them to use it properly in any adequate situation
NOTE:-		Building Premises is below 9 mtr. Height		

